

Part-I
PROFORMA FOR THE SAFETY OF SCHOOL BUILDING
(TO BE FILLED BY THE HEAD OF SCHOOL/INSTITUTE)

326
28-9-2020

- | | | |
|----|---|---|
| 1 | Name of the School | TAGORE PUBLIC SCHOOL |
| 2 | Location | AGGAR NAGAR, BLOCK-A, FERAZEPUR ROAD,
LUDHIANA |
| 3 | Plot Area | 6454 S. YARDS |
| 4 | Plinth Area | 3333 S. YARDS |
| 5 | Timber of Story | DOUBLE STOREY |
| 6 | Year of Construction of Building | 1975 |
| 7 | Provision of the Qualification engineer the following Detail | |
| a | Name of the Engineer with Qualification | MR. KRISHAN KUMAR, CIVIL ENGINEER |
| b | Address of the Engineer | THE LDH AGG. CO-OP H/B SOCIETY LTD. AGGAR NAGAR, LUDHIANA |
| c | Set of structure Drawing used in the Construction if available | |
| d | Name of Architect | |
| 8 | Whether the building has been constructed for the purpose of: | |
| a | School | (Yes/No) ✓ |
| b | Residential purpose and converted For use as a school | (Yes/No) ✓ |
| 9 | Materials used for roof | |
| a | R.C.C. Slabs | (Yes/No) ✓ |
| b | R.S. Joints and Battens | (Yes/No) ✓ |
| 10 | Material used for Walls | |
| a | Mud Mortar | (Yes/No) ✓ |
| b | Cement Mortar | (Yes/No) ✓ |
| c | Plaster | |
| | i) Lime Mortar | (Yes/No) ✓ |
| | ii) Cement Mortar | (Yes/No) ✓ |
| 11 | Flooring | |
| a | Conglomerate | (Yes/No) ✓ |
| b | Terazzo | (Yes/No) ✓ |
| c | Brick Paving | (Yes/No) ✓ |
| 12 | Detailed Drawing indicating dimensions of the Rooms Along with size and location of doors and window. | |

M. Kamal
PRINCIPAL
TAGORE PUBLIC SCHOOL
AGGAR NAGAR, LUDHIANA

Part-I

(To be Filed by S.D.E of P.W.D B & R Department)

A) I have visited the above mentioned School on 31/8/2020 and have visually impacted it from all angles of safety and I found fit for normal use as school building.

B) In case any additional/alteration of expansion and modification of this building is to be carried out the same be carried out under the supervision of a technically specified Engineer and this certificate may again be obtained after the completion of work from the undersigned.

C) In case the building is affected by flood or if there is settlement of walls/foundation or eaving of roof etc. Immediately inspection of the undersigned by the arranged to check the stability and safety of the building.

D) This building can be safe by the occupied for normal use upto 31/3/2021 (indicate year upto which it can be used).

Signature
Date
Place

1. ✓ डी.एच. 322-22 मिडी - 28/09/2020
धुमीयल टेंगो चर्चलिन मसुल, अगार-ठगर लुपिकाहा नी डी
मुळल गिंत डेसिका सरा डी।

2. डी.एच. रावपरागी टिमीलीकर, डुमारी नं. 1, लुपिकाहा
नी डी मुळल अडे अगलेगी रावहाली गिंत डेसिका सरा
डी।

Signature
Date
Place